



FIG. 1



00000000000000000000000000000000

[illegible]

202010" 4306E660
144221" 4306E660



Device, And Method For Trenchless
Replacement Of Underground Pipe
Carter, et al.
S/N 09/939,084
Atty. Docket #16279-14C1
3/18






FIG. 6




FIG. 7




FIG.8




FIG.9




FIG.10




FIG. 11

0939084.032401
0939084.010702




FIG. 13




FIG. 12

2020101806660
2020101806660



00939084 " 010702




FIG. 16

202010" 4806E660
202010" 4806E660




FIG. 17




FIG. 18

FIG. 19






FIG.21

14/18




FIG. 22




FIG. 23




FIG. 24

207010-1806E660
0939084-010701




FIG.25




FIG.26




FIG.27

0939084.010702
48062650
48062650





FIG.30





FIG.31



2020101806E660
10423304306E660

202010" 4806E660
204280" 4806E660




FIG.32

FIG.33